


User's Guide



Heavy Duty Wood Moisture Meter

Model 407777



Test Equipment Depot

1-800-517-8431

99 Washington Street
Melrose, MA 02176
Phone 781-665-1400
Toll Free 1-800-517-8431



Visit us at www.TestEquipmentDepot.com



[Back to the Extech 407777 Product Page](#)

Introduction

Congratulations on your purchase of the Extech 407777 Wood Moisture Meter. This meter measures the moisture content of wood as a percentage. Measurements are made using the supplied remote intrusive sensor. Careful use of this meter will provide years of reliable service.

Specifications

General Specifications


Circuit	Custom one-chip LSI microprocessor circuit
Display	Dual function 2000 count (0 to 1999) LCD display
Measurement Range	9% to 30% Moisture Content
Memory Table	9 memory groups for approx. 150 species of wood
Data Hold	Front panel push-button freezes displayed reading
Sample Rate	Approx. 0.8 seconds
Sensor Structure	Remote two-prong intrusive sensor
Memory Record / Recall	Records Maximum/Minimum readings for later recall
Auto Power off	Meter automatically shuts off after 10 minutes
Data Output	RS-232 PC serial interface for use with Model 407001 data acquisition software and interface cable kit
Operating Temperature	32°F to 122°F (0°C to 50°C)
Operating Humidity	90% Relative Humidity (max.)
Power Supply	9V battery
Power Current	Approx. 5.8mA DC
Weight	0.73 lbs (330g) (including batteries & probe)
Size	Main instrument: 7.1 x 2.8 x 1.3" (180 x 72 x 32 mm) Probe: 0.9" (23mm) diameter x 6.54" (23mm) length
Accessories	Spare pins (10) and protective rubber holster

Range Specifications

Measurement	Range	Resolution	Accuracy
Moisture content	9 to 30%	0.1 %	± (4% + 5d)
Temperature compensation: 32°F to 122°F (0°C to 50°C)			

Meter Description

1. Sensor input: Use caution when inserting the sensor.
2. PC interface jack: For use with Model 407001 software and interface cable kit
3. LCD Display: Displays moisture content, temperature compensation, units of measure, and function symbols
4. Push-buttons (see below):
 - Power: Turn meter on and off
 - Hold: Freeze displayed reading
 - Material: Select material group 1 through 9 (see Table in the Appendix)
 - Record: Track the highest (MAX) and lowest (MIN) readings
 - Recall: Review the MAX and MIN readings
 - Calibration and '+': Used to calibrate the meter (refer to the calibration section)
 - Temperature Adjust: Used for temperature compensation function (refer to temperature compensation section in this manual)
5. Battery compartment (back): Remove the rubber protective holster to access the rear battery compartment
6. Protective holster: Rubber jacket insulates meter
7. Sensor pins: Replaceable sensor tips
8. Sensor handle: Hold the sensor by the handle when taking measurements



Preparation

1. Insert the sensor into the sensor input jack on the meter top
2. Ensure that a fresh 9V battery is installed by powering the unit, observing that the LCD illuminates, and that the low battery indicator **LBT** is off. To access the rear battery compartment, the meter's protective rubber jacket must be removed.
3. Remove the rubber pin protector from the sensor pin tips before use.
4. Note that this meter automatically turns off after 10 minutes to conserve battery life. To defeat this feature, press the RECORD key to access the data recording mode. In the recording mode, the automatic power off feature is disabled. For more on the recording mode, refer to the section 'Maximum and Minimum Record and Recall' later in this manual.

Wood Moisture Measurements

Wood moisture measurements for known wood type

1. Press the POWER button to turn on the meter.
2. Use the Material button to select a wood group (refer to the material list in the Appendix later in this manual). Select group 1 through 9 for general woods or Group 9 for chipboard.
3. Insert the sensor's test pins into the wood under test.
4. Insertion should be to at least a 0.08" (2mm) depth for highest accuracy. If this is not possible, carefully insert the test pins as far as possible without using undue force.
5. The meter display will now indicate moisture content in %.
6. If the moisture content is greater than 30% the display will indicate dashes at the top of the LCD display (-----).
7. If the moisture content is less than 9% the display will indicate dashes along the bottom of the LCD display (_ _ _ _ _).

Wood moisture measurements for unknown wood type

Note that this method is used for reference only. Measurements of known wood types have a higher accuracy than measurements of unknown wood types.

1. Turn ON the meter.
2. Select Material Group 1 using the Material select button.
3. Insert the sensor's test pins into the material under test.
4. Insertion should be to at least a 0.08" (2mm) depth. However, if this is not possible, carefully insert the test pins as far as possible without using undue force.
5. The meter display will now indicate moisture content in %.

Wallboard Moisture Measurements

Unlike wood types which have known densities, wallboard does not. Consequently it is not possible to get an absolute moisture content reading.

The following procedure can be used to make relative or comparative measurements of the moisture content in wallboard.

1. Turn ON the meter.
2. Select Material Group 1 by pressing the Material Select button.
3. Insert the sensor's test pins into a known dry area of wallboard. Insertion should be to at least a 0.08" (2mm) depth. The meter display will now indicate moisture content in %. Note this 'dry' reading.
4. Insert the sensor's test pins into the wallboard under test. Insertion should be to at least a 0.08" (2mm) depth. The meter display will now indicate moisture content in %. Note this 'moist' reading.
5. Compare the 'dry' wallboard reading with the 'moist' wallboard reading to determine the moisture content of the wallboard area under test.

Temperature Compensation

This meter is calibrated for use at ambient temperature: 68°F (20°C). When the temperature is above or below this value, manual temperature compensation should be performed to maintain meter measurement accuracy. Follow these steps:

1. Check that the RECORD function is not engaged ('REC' display icon is off).
2. Use the TEMPERATURE ADJUST buttons to increase (left button) or decrease (right button) the temperature display to match the new temperature (in °C). The temperature is adjustable in 1 degree steps.
3. The value will be stored after 4 seconds. Temperature compensation adjustments are not stored in memory when the meter is turned OFF however.

Data Hold

To freeze the LCD display reading, press the HOLD key. The 'DH' icon will appear on the LCD. Press the HOLD key again to return to normal operation (the 'H' hold icon will switch OFF).

Maximum (MAX) and Minimum (MIN) Record and Recall

To keep track of the highest (MAX) and lowest (MIN) measurements, follow the procedure below:

1. Press the RECORD button to begin tracking the highest and lowest readings. The REC display icon will appear on the LCD.
2. Press the RECALL key when it is desired to view the highest reading since the RECORD button was pressed. The MAX icon will appear on the display and the reading shown will be the highest reading encountered since the RECORD key was pressed.
3. Press the RECALL key again to view the lowest reading (MIN).
4. To exit this mode of operation, press the RECORD key again. The REC, MAX, and MIN icons will switch off.

Battery Replacement

When the low battery indicator **LBT** appears, the 9V battery should be replaced.

1. Remove the rubber protective holster that surrounds the meter.
2. Remove the battery compartment cover, located on the lower back of the meter, with a coin or a flathead screwdriver.
3. Replace the 9V battery.
4. Close the battery compartment and affix the protective holster.

RS-232 PC Interface

The Meter includes a PC interface for use with optional Data Acquisition Software and interface cable kit (Part Number 407001). Operational instructions for the interface and software are supplied with the optional interface kit.

Calibration

Calibration Verification

1. Ensure that the RECORD function is not engaged (REC icon is not on the LCD).
2. Select Material Group 1 using the Material Select button.
3. Press and hold both the CALIBRATION and the "+" buttons.
4. The display will begin to count down from 5 to 1.
5. If the meter's existing calibration is correct, the LCD will display "good"
6. If the meter's existing calibration is incorrect, the LCD will display "Err".
7. If the calibration is incorrect follow the steps in the next section to recalibrate.

Calibration Procedure

1. Remove the Meter's protective rubber holster.
2. Select Material Group 1 via the Material Select button.
3. Remove the rear battery compartment cover and locate the VR1 potentiometer that sits inside the battery compartment on the left side.
4. Press and hold the "+" Calibration button.
5. Adjust VR1 for a display of "18.0".



99 Washington Street
Melrose, MA 02176
Phone 781-665-1400
Toll Free 1-800-517-8431



Visit us at www.TestEquipmentDepot.com



Back to the [Extech 407777 Product Page](#)

Test Equipment Depot, 99 Washington Street, Melrose, MA 02176
781.665.1400 | 800.517.8431 | Fax: 781.665.0780

Appendix - Table of Material Groups (alphabetized) with Group Numbers

Abura	4	Erimado	5	Meranti, Red (light or dark)	2	Pine, Ponderosa	3
Afara	1	Fir, Douglas	2	Meranti, white	2	Pine, Radiata	1
Afrosmosia	6	Fir, Grand	1	Merbau	2	Pine, Carribean, pitch	3
Afzelia	4	Fir, Noble	8	Missanda	3	Poplar, Black	1
Agba	8	Gegu, Nohor	7	Muhuhi	8	Pterygota, African	1
Amboyna	6	Greenheart	3	Muninga	6	Pyinkado	4
Ash, European	1	Guarea, Black	8	Musine	8	Queensland Walnut	3
Ash, Japanese	1	Guarea, White	7	Musizi	8	Queensland Kauri	8
Ash, American	2	Gum, American Red	1	Myrtle, Tasmanian	1	Ramin	6
Ayan	3	Gum, Saligna	2	Niangon	3	Redwood, Baltic (Europe)	1
Baguacu, Brazilian	5	Gum, Southern	2	Oak, Japanese	1	Redwood, Californian	2
Balsa	1	Gum, Spotted	1	Oak, Tasmanian	3	Redwood, Baltic (Europe)	1
Bange Wanga	1	Gurjun	1	Oak, Turkey	4	Rosewood, Indian	1
Basswood	6	Hemlock, Western	3	Oak, American Red	1	Santa Maria	7
Bech, European	3	Hickory	5	Oak, American white	1	Sapele	3
Berlina	2	Hyedunani	2	Oak, European	1	Seraya, Red	3
Binvang	4	Iroko	5	Obeche	6	Silky Oak, African	3
Birch, European	8	Ironbank	2	Odoko	4	Silky Oak, Australian	3
Birch, Yellow	4	Jarrah	3	Okwen	2	Spruce, Norway (European)	3
Bisselon	4	Jelutong	3	Olive E. African	2	Spruce, Sitka	3
Bitterwood,	5	Kapur	1	Olivillo	6	Sterculia, Brown	1
Blackbutt	3	Karri	1	Opepe	7	Stringybar, Yellow	3
Bosquiea	1	Kauri, New Zealand	4	Padang	1	Stringybark, Messmate	3
Boxwood, Maracaibo	1	Kauri, Queensland	8	Padauk, African	5	Sycamore	5
Cahoma	1	Keruing	5	Panga Panga	1	Tallowwood	1
Camphorwood, E. African	3	Kuroka	1	Persimmon	6	Teak	5
Canarium, African	2	Larch, European	3	Pillarwood	5	Totara	4
Cedar, West Indian	8	Larch, Japanese	3	Pine, Maritime	2	Turpentine	3
Cedar, Western Red	3	Larch, Western	5	Pine, Nicaraguan Pitch	3	Utile	8
Cherry, European	8	Lime	4	Pine, American Long Leaf	3	Walnut Queensland	3
Chestnut	3	Loliondo	3	Pine, Corsican	3	Walnut, European	3
Chipboard	9	Mahogany, West Indian	2	Pine, Yellow	1	Walnut, African	8
Coachwood	6	Mahogany, African	8	Pine, Hoop	3	Walnut, N. Guinea	2
Cordia, American light	5	Makore	2	Pine, Kauri	4	Walnut, American	1
Cypress, E. African	1	Mansonia	2	Pine, Huon	2	Wandoo	8
Danta	3	Maple, Pacific	1	Pine, Scots	1	Wawa	6
Douglas Fir	2	Maple, rock	1	Pine, Lodgepole	1	Whitewood	3
Elm, English	4	Maple, Queensland	2	Pine, Sugar	3	Yew	3
Elm, Rock	4	Maple, Sugar	1	Pine, New Zealand, White	2		
Elm, White	4	Matai	4	Pine, Parana	2		