





Humidity Meters

Selection Guide







%RH	Temperature	Dew Point	Wet Bulb	IR Thermometer	Max /Min	Differential Temperature	External Temp. Probe Available	Remote Probe	Calibration Solutions Available	Big Digit Display	Datalogging	PC Interface	Graphical Display	Audible and/or Visual Alarm	Real Time Stamp	NIST Available	Time / Stopwatch	Air Velocity
-----	-------------	-----------	----------	----------------	----------	--------------------------	--------------------------------	--------------	---------------------------------	-------------------	-------------	--------------	-------------------	-----------------------------	-----------------	----------------	------------------	--------------





Psychrometers

				RH300	•	•	•	•	•	•	•							
				RH350	•	•	•	•	•	•	•				•	•		
				RH390	•	•	•	•	•							•		
				RH401	•	•	•	•	•		•					•		





Hygro-Thermometers

				RH101	•	•			•	•								
				4465CF	•	•										•		
				445580	•	•		•		•						•		
				44550	•	•		•										





Dataloggers

				EA20	•	•	•	•	•	•	•							
				EA25	•	•	•	•	•	•	•							
				RH520	•	•	•	•	•	•	•		•	•	•	•	•	
				42270/75	•	•				•	•		•	•				
				407445	•	•		•	•	•	•		•			•		

Indicators

				445702	•	•		•										•
				445703	•	•		•		•								
				445715	•	•		•	•	•						•		
				445814	•	•	•	•		•				•				
				445815	•	•	•	•	•	•				•		•		

Specialty Meters

				HW30	•	•									•	•		
				45158	•	•	•											•
				45160	•	•		•	•									•
				407412	•	•		•	•		•				•			•

Distributed by: