



#45-332

## Fiber Inspection Microscope Operation Manual

Thank you for purchasing the **IDEAL Fiber Inspection Microscope**.

This instrument was designed to provide years of service while delivering true optical performance. This instrument can be configured for either 100x or 200x magnification, depending upon the eyepiece used (10x or 20x). A universal 2.5mm connector adapter is included with the microscope and various other universal or dedicated, interchangeable adapters can be purchased for use with the microscope. This manual will provide you with the necessary information of the operation and maintenance of your new IDEAL Fiber Inspection Microscope.

### User Safety Warning



**DO NOT** use the Fiber Inspection Microscope to view active fiber signals under ANY circumstances. Active fiber signals contain laser light, and direct eye contact with laser light should be avoided. The failure to avoid direct eye contact with laser light can result in serious damage to the eye. The Fiber Inspection Microscope may magnify the laser light in active fiber signals; direct eye contact with magnified laser light should be avoided. Laser safety filters, as used on the Fiber Inspection Microscope, are no substitute for practicing good laser safety. If you are unfamiliar with laser safety practices, seek out professional training. There are many capable trainers working in the fiber optic field who can help.



*This manual will explain the general use of the Fiber Inspection Microscope. However, it is important to read the specific termination instructions published by the manufacturer of the connector you are using. This will ensure proper termination. Also, be sure you have read the User Safety Warning and fully understand that direct eye contact with laser light and magnified laser light should be avoided.*

### SETUP

#### Changing the Connector Adapter

The Fiber Microscope comes fully assembled. Just remove the instrument from its case, and it's ready to



### OPERATION

#### 1. Load the Fiber into the Adapter

Load the polished connector into the 2.5mm Universal Adapter (Part #693.008). Simply slide the ferrule (2.5mm) into the adapter port until you feel it hit a stop. It may require a little pressure to get it started as our adapter is equipped with a no-slip gripping mechanism.



It is important to slide the ferrule all the way to the stop. This will minimize any refocusing that needs to be done when changing from one connector to the next. If you have purchased one of the dedicated adapters, insert the connector just as you would into a patch bay or mated connector.

#### Special Instructions

##### MTRJ Adapter

When using the MTRJ adapter, only one fiber will be visible at a time. In order to inspect each fiber, insert the connector and view the first fiber. Then, remove

the connector from the adapter, rotate it 180°, insert again, and view the other fiber.

### 2. Turn the light on.

The light operates by pressing and holding the light switch.



Light Switch

### 3. Focus and view.

Once the connector is loaded and the light is on, hold the eyepiece up to your eye and begin focusing. Grip the focusing eyepiece and turn it to focus the image.

The first time you use the microscope, it may take a little longer to find the image. Once you find the image, very little refocusing is necessary if the connector is properly loaded.



Image at 100x

#### Hint:

If you have trouble finding the image, there is a simple trick. Load the connector and check to see that the light is on. Then turn the "Focus Adjustment" clockwise until you feel the tube hit a stop. At this point, the objective is actually just touching the sample. If you look in the eyepiece, the image will be dim or black. Now look into the microscope and begin slowly turning the tube counter-clockwise. This will slowly back the lens away from the sample and at some point the fiber should come into view.

## SERVICE AND MAINTENANCE

### Changing the Batteries

1. Remove the battery cap and the three used batteries.


2. Replace with three type "LR44" batteries as shown above.

3. Replace the battery cap.



### Changing the Eyepiece

1. Slide the rubber Eyecup off of the Focusing Tube.
2. After the Eyecup is removed, unscrew the Eyepiece from the Focusing Tube.
3. Replace the Eyepiece and the Eyecup.



#### MAINTENANCE

Keep this instrument clean and dry. It is built for durability and field use, but careful operation will greatly extend life.

### PARTS AND ACCESSORIES

Eyepiece 10x	693.007
Eyepiece 20x	45-336

#### Connector Adapters

Universal Adapter (2.5mm) (For FC,SC,ST connectors.)	693.008
---	---------

Universal Adapter (1.25mm)	45-334
----------------------------	--------

(For LC or MU connectors.)

MTRJ Adapter	45-335
--------------	--------