

## Non-contact Photo Tachometer Adaptor

Measure from 100 to 19990rpm

### Features:

- 0.1mV/rpm output when plugged into a multimeter
- 1.2% basic accuracy
- Dims: 6.7x2.9x1.5" (170x74x38mm)
- Weight: 8oz (227g)
- Complete with 4.5ft (1.4m) cable and banana plugs, 23" (0.6m) reflective tape, and 4 AA batteries

CE



### Ordering Information:

461900 .....Non-contact Photo Tachometer Adaptor

